

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402778375

Date Received:  
08/12/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Victoria Dizghinjili</u>	<u>303-825-4822</u>	<u>vdizghinjili@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 688000543  
Inspection Date: 06/04/2021 FIR Submit Date: 06/10/2021 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 319921

Location Name: GREEN-61S67W Number: 18NENW County: \_\_\_\_\_  
Qtrqr: NENW Sec: 18 Twp: 1S Range: 67W Meridian: 6  
Latitude: 39.970104 Longitude: -104.933482

FACILITY - API Number: 05-001-00 Facility ID: 319921

Facility Name: GREEN-61S67W Number: 18NENW  
Qtrqr: NENW Sec: 18 Twp: 1S Range: 67W Meridian: 6  
Latitude: 39.970104 Longitude: -104.933482

CORRECTIVE ACTIONS:

2  CA# 151840

Corrective Action: Control the source of the leaking fluid, clean up impacted soils and properly dispose per Rule 906. Date: 06/18/2021

Response: CA COMPLETED Date of Completion: 08/09/2021

Operator Comment: Mechanical issue has been fixed. Stained soil has been removed at pumping unit motor. Please see the attached pictures.

COGCC Decision: Approved

COGCC  
Representative:

3  CA# 151841

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 06/25/2021

Response: CA COMPLETED

Date of Completion: 08/09/2021

Operator Comment: Mechanical issue has been fixed. Stained soil has been removed at pumping unit motor. Please see the attached pictures.

COGCC Decision: Approved

COGCC  
Representative:

4  CA# 151842

Corrective Action: Install sign at wellhead.

Date: 06/25/2021

Response: CA COMPLETED

Date of Completion: 08/09/2021

Operator Comment: New well sign has been installed. Please see attached picture.

COGCC Decision: Approved

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: \_\_\_\_\_

Title: Engineering Tech

Date: 8/12/2021 12:26:18 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402778375	FIR RESOLUTION SUBMITTED
402778443	New sign installed PIC1
402778444	Stained soil removed PIC2

Total Attach: 3 Files