

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/14/2021

Submitted Date:

10/19/2021

Document Number:

701102064

**FIELD INSPECTION FORM**

Loc ID 314339 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10654  
Name of Operator: LASSO OIL & GAS LLC  
Address: 3021 RIDGE RD #156  
City: ROCKWALL State: TX Zip: 75032

**Findings:**

- 9 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name     | Phone          | Email                            | Comment         |
|------------------|----------------|----------------------------------|-----------------|
| , Engineering    |                | dnr_cogccengineering@state.co.us | All engineering |
| Pesicka, Conor   |                | conor.pesicka@state.co.us        |                 |
| Rosenberg, Kelly |                | kelly.rosenberg@state.co.us      |                 |
| Boulger, Levin   | 970-509-0256   | lboulger@31operating.com         |                 |
| Thompson, Bud    |                | BLThomps@BLM.gov                 |                 |
| Freeman, Kris    | (254) 717-0435 | kfreeman@31operating.com         |                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 228448      | WELL | SI     | 07/01/2020  | OW         | 103-05301 | ARROWHEAD 9   | SI          |

**General Comment:**

[COGCC Follow Up Inspection Report Summary](#)  
Follow up to 02/17/2021 inspection # 700405450  
During this inspection the following compliance issues were observed:

- [Dead weed debris on location.](#)
- [Braden open to atmosphere](#)
- [Heat elements out of tanks and tanks are open access of birds and wild life.](#)
- [Spill catch pan on load line has product in it.](#)

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

Overall Good:

**Signs/Marker:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | BATTERY  |       |            |
| Comment:           |  |       |            |
| Corrective Action: |  | Date: |            |
| Type               | TANK LABELS/PLACARDS                                 |       |            |
| Comment:           | Capacity faded, no operator name and contact number. |       |            |
| Corrective Action: | Install sign to comply with Rule 605.h.              | Date: | 01/20/2022 |
| Type               | WELLHEAD   |       |            |
| Comment:           |  |       |            |
| Corrective Action: |  | Date: |            |

**Emergency Contact Number:**

|                    |     |       |  |
|--------------------|-----|-------|--|
| Comment:           | 911 | Date: |  |
| Corrective Action: |     | Date: |  |

**Good Housekeeping:**

|                    |                               |       |            |
|--------------------|-------------------------------|-------|------------|
| Type               | UNUSED EQUIPMENT              |       |            |
| Comment:           |                               |       |            |
| Corrective Action: |                               | Date: |            |
| Type               | DEBRIS                        |       |            |
| Comment:           | Dead weed debris on location. |       |            |
| Corrective Action: | Comply with Rule 606          | Date: | 03/12/2021 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                     |     |       | corrective date |
|--------------------------|-----|-------|-----------------|
| Type: Deadman # & Marked | # 4 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |
| Type: Bird Protectors    | #   |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |
| Type: Pump Jack          | # 1 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |
| Type: Bradenhead         | #   |       |                 |

|                    |   |       |            |
|--------------------|---|-------|------------|
| Comment:           | Open to atmosphere. No braden access.   |       |            |
| Corrective Action: | Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) | Date: | 10/29/2021 |

**Tanks and Berms:**

| Contents           | #  | Capacity | Type             | Tank ID | SE GPS |            |
|--------------------|--|----------|------------------|---------|--------|------------|
| CRUDE OIL          | 1  | 400 BBLs | HEATED STEEL AST |         |        |            |
| Comment:           | Heat elements out of tanks and tanks are open access of birds and wild life. |          |                  |         |        |            |
| Corrective Action: | Cover opening to prevent entry of birds and other wild life.                 |          |                  |         | Date:  | 11/05/2021 |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type               | Capacity  | Permeability (Wall) | Permeability (Base) | Maintenance |            |
|--------------------|---|---------------------|---------------------|-------------|------------|
| Earth              |   |                     |                     |             |            |
| Comment:           | Spill catch pan on load line has product in it. Stained ground at heat element of tank. |                     |                     |             |            |
| Corrective Action: | Remove product from spill catch pan. Remove stained ground.                             |                     |                     | Date:       | 11/05/2021 |

**Venting:**

|                    |       |
|--------------------|-------|
| Yes/No             |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 228448 Type: WELL API Number: 103-05301 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 701102073    | Inspection 701102064 photo log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5558635">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5558635</a> |