

# Inspection Photos

10/18/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 336014

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 336014



October 18, 2021  
39 53845326N 107 69796061W



October 18, 2021  
39 53847197N 107 69793164W

**Photo 1:** Photos taken from the spill area with impacts to both upland and wetland areas south of the Location. Areas will require reclamation upon closure of the project.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 336014



**Photo 2:** Photos taken from the spill area with impacts to both upland and wetland areas south of the Location. Areas will require reclamation upon closure of the project.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 336014



October 18, 2021  
39.53832987N 107.69783923W



October 18, 2021  
39.5458915N 107.6524228W

**Photo 3:** Photos show vegetation in the immediate areas adjacent to the spill area. Vegetation observed fairly consistent with wetland habitats; vegetation observed predominantly *Carex* and *Juncus* species. *Typha* was observed though in low densities; patches of dense *Phragmites*. Vegetation observed in the adjacent undisturbed upland areas predominantly consists of *Distichlis spicata*, *Chrysothamnus* sp. and various wheatgrass species.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 336014



**Photo 4:** Photo taken from the interim areas west of the Location. Some areas have been disturbed during spill response. Areas will require additional reclamation.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 336014



**Photo 5:** Photo taken from the southern interim areas of the Location, facing east. Photo shows interim areas (left of line) are predominately undesirable plant species such as Kochial and Salsola sp. Undisturbed upland areas (right of line) are predominantly saltgrass, wheatgrass and shrub species. Interim areas are not progressing towards 1003 standards.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 336014



**Photo 6:** Continued from 5. Photo taken from the southeaster interim areas of the Location, facing west. Photo shows interim areas (right of line) are predominately undesirable plant species such as Kochial and Salsola sp. Undisturbed upland areas (left of line) are predominantly saltgrass, wheatgrass and shrub species. Interim areas are not progressing towards 1003 standards.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 336014



**Photo 7:** Photo shows compare/contrast of interim areas not progressing towards 1003 standards, and the adjacent reference.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 336014



**Photo 8:** Photo shows example of anchors observed on the Location not properly marked.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 336014



October 18, 2021  
39.53895392N 107.69747497W



October 18, 2021  
39.53901941N, 107.69738731W

**Photo 9:** Photos show gas observed leaking from the A4 and A1 wells.