

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NWNW

Location ID: 335395



Photo #5076 from entrance to location.



Photo #5077 Glycol storage tank missing required information.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NWNW

Location ID: 335395



Photo #5078 Rill erosion occurring on location.



Photo #5079 insufficient velocity checks in ditch.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NWNW

Location ID: 335395



Photo #5081 Rill erosion occurring in ditch.