

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /34SWNW

Location ID: 335254



Photo #5082 from entrance to location.



Photo #5083 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /34SWNW

Location ID: 335254



Photo #5084 Glycol storage tank missing required information.



Photo #5085 Run on to location is not being controlled.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /34SWNW

Location ID: 335254



Photo #5086 Rill erosion occurring on location.



Photo #5087 Sediment encroaching on equipment.