

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/19/2021

Submitted Date:

10/19/2021

Document Number:

700703389

**FIELD INSPECTION FORM**

Loc ID: 335711      Inspector Name: Ramsey, Scott      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH      State: TX      Zip: 76102

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Thomson, Bud		BLThomps@BLM.gov	
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278098	WELL	SI	07/01/2021	GW	103-10589	PICEANCE CREEK UNIT T62X-11G2	SI
278099	WELL	SI	08/01/2021	GW	103-10588	PICEANCE CREEK UNIT T62X-11G1	SI
278135	WELL	PR	03/01/2019	GW	103-10591	PICEANCE CREEK UNIT T62X-11G3	PR

**General Comment:**

COGCC Inspection Report Summary  
On Monday 10/18/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus PCU T62X-11G, at Location # 335711 in Rio Blanco county Colorado.  
While there, I observed normal operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.  
During this inspection the following compliance issues were observed:

1. Lack of battery signage
2. Areas of fill slope show signs of erosion/sediment migration and areas of cut slope show signs of lack of stabilization.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Comply with rule 605.e		Date: 12/24/2021
Type	OTHER		
Comment:	Entrance to well heads		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 3		
Comment:			
Corrective Action:			Date:

Type: Other	# 1		
Comment:	Well head T/A'd		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Storage building		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	One plastic chemical tank in plastic containment and One 500 gallon methanol tank in metal containment		
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 278098 Type: WELL API Number: 103-10589 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last production record well produced 6/2021

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 278099 Type: WELL API Number: 103-10588 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last production record well produced 7/2021

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 278135 Type: WELL API Number: 103-10591 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				

Comment: [1. Areas of fill slope show signs of erosion/sediment migration and areas of cut slope show signs of lack of stabilization.](#)

Corrective Action: [Install or repair required BMPs](#)

Date: 12/24/2021

**Pits:**  NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	436815	2148354	
	278621	1417859	
	436815	2148354	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703393	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5559266">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5559266</a>