

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/12/2021

Submitted Date:

10/13/2021

Document Number:

700703365

FIELD INSPECTION FORMLoc ID 335227 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, COGCC		shaun.kellerby@state.co.us	
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211169	WELL	PR	06/24/1995	GW	045-06928	BROOME 1	PR
275528	WELL	PR	08/04/2009	GW	045-10341	GGU BROOME 43A-30-691	PR
275529	WELL	PR	07/01/2020	GW	045-10342	GGU BROOME 44C-30-691	PR
275530	WELL	PR	08/04/2009	GW	045-10343	GGU BROOME 44A-30-691	PR
275531	WELL	PR	08/23/2010	GW	045-10344	GGU BROOME 34C-30-691	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 10/12/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a follow up inspection #3 at TEP Broome 1, at Location # 335227 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.

C/A's (Cut slope stabilization riling is present) from document # 700702048 and document # 700702702 have not been completed C/A date remains the same (1/21/2021).

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Horizontal units that include glycol storage tanks, storage vessels have labeling, but are missing information.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	#		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	200 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>211169</u>	Type: <u>WELL</u>	API Number: <u>045-06928</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>
Facility ID: <u>275528</u>	Type: <u>WELL</u>	API Number: <u>045-10341</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>
Facility ID: <u>275529</u>	Type: <u>WELL</u>	API Number: <u>045-10342</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>
Facility ID: <u>275530</u>	Type: <u>WELL</u>	API Number: <u>045-10343</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>
Facility ID: <u>275531</u>	Type: <u>WELL</u>	API Number: <u>045-10344</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Culverts						
		Ditches				
Berms						
Ditches						

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.
C/A's (Cut slope stabilization riling is present) from document # 700702048 and document # 700702702 have not been completed C/A date remains the same (1/21/2021).

Corrective Action: **Install or repair required BMPs**

Date: 01/21/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402843176	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5556132
700703366	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5556127