

**Inspection Photos**  
**Location Name: Seltzer #1-A**  
**Location ID: 311297**



**Photo 1 Unused equipment: Electric control box, Pumping unit.**



**Photo 2 Unused equipment electric meter and electric panel.**

**Inspection Photos**  
**Location Name: Seltzer #1-A**  
**Location ID: 311297**



**Photo 3 Guyline anchor not properly marked.**



**Photo 4 unused equipment fencing and gate. Trash and debris.**



**Inspection Photos**  
**Location Name: Seltzer #1-A**  
**Location ID: 311297**



**Photo 5 Guyline anchor not properly marked.**



**Photo 6 Guyline anchor not properly marked.**

**Inspection Photos**  
**Location Name: Seltzer #1-A**  
**Location ID: 311297**



**Photo 7 Debris: dead weeds on access road. Road not properly maintained.**



**Photo 8 Loc pic of unused equipment.**



**Inspection Photos**  
**Location Name: Seltzer #1-A**  
**Location ID: 311297**



**Photo 9 TNK BTRY**



**Photo 10 TNK BTRY**

**Inspection Photos**  
**Location Name: Seltzer #1-A**  
**Location ID: 311297**



**Photo 11 Production equipment**



**Photo 12 HOZ Sep not in use fuel gas line is in closed position.**



**Inspection Photos**  
**Location Name: Seltzer #1-A**  
**Location ID: 311297**



**Photo 13 Supply line for HOZ Sep in closed position.**




**Photo 14 Gas sales inlet to meter is LOTO**

**Inspection Photos**  
**Location Name: Seltzer #1-A**  
**Location ID: 311297**



**Photo 15 Gas sales line outlet from meter LOTO**



**Photo 16 Sales gas meter calibration card has not been calibrated since 2016.**



**Inspection Photos**  
**Location Name: Seltzer #1-A**  
**Location ID: 311297**



**Photo 17 well site. Debris: Dead weeds on location**



**Photo 18 un used equipment: PU parts and fencing.**