

# Inspection Photos

API: 071-06128

Operator: OGRIS OPERATING LLC

Inspection Date: 10/21/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 10/21/2021

## Inspection Photos



**Photo 1.** There has been road base spread on areas where vehicle rutting had occurred. The road has been regraded and repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 10/21/2021

## Inspection Photos



**Photo 2.** The culvert inlet has been cleaned out and repaired.



**Photo 3.** The culvert outlet has been repaired to allow stormwater diversion. Disturbance area was seeded and stabilized.



## Inspection Photos



**Photo 4.** Facing north as the road ascends the hill side. A culvert has been installed at red arrow to properly divert stormwater away from the road.



**Photo 5.** The culvert outlet gabion has been installed. This structure will need to be monitored and maintained to prevent sediment accumulation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 10/21/2021

## Inspection Photos



**Photo 6.** There has been road base spread on areas where vehicle rutting had occurred. The road has been regraded and repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 10/21/2021

## Inspection Photos



**Photo 7.** Facing northwest further along the road. There is vehicle rutting in this area which was not graveled. Additional gravel is needed in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 10/21/2021

## Inspection Photos



**Photo 8.** The road was graded along this area. The pieces of blue pipe debris were removed from this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 10/21/2021

## Inspection Photos



**Photo 9.** The area of erosion previously observed was repaired and stabilized with straw blanket.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 10/21/2021

## Inspection Photos



**Photo 10.** Facing southeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 10/21/2021