

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2021

Submitted Date:

10/22/2021

Document Number:

695105014

**FIELD INSPECTION FORM**

Loc ID 308363 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD State: CO Zip: 8111-

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Fitzgerald, Edie	719-859-1394	efitzgerald@ogrisop.com	<a href="#">All Inspections</a>
GEE, GREG	903-987-0353	ggee@ogrisop.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269064	WELL	PR	08/09/2011	GW	071-07901	APACHE CANYON 1-5	PR
292646	PIT	AC	09/05/2008		-	APACHE CANYON 01-05	AC

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Type: Compressor	# 1	Comment:	Corrective Action:	Date:	
Type: Prime Mover	# 1	Comment:	Corrective Action:	Date:	
Type: Pump Jack	# 1	Comment:	Corrective Action:	Date:	
Type: Bradenhead	# 1	Comment: IS PLUMBED TO SURFACE	Corrective Action:	Date:	
Type: Vertical Separator	# 1	Comment:	Corrective Action:	Date:	
Type: Ancillary equipment	# 1	Comment: TELEMETRY EQUIPMENT	Corrective Action:	Date:	
Type: Deadman # & Marked	# 4	Comment:	Corrective Action:	Date:	
Type: Gas Meter Run	# 1	Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.	Corrective Action:	Date:	

**Venting:**

Yes/No NO

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 269064 Type: WELL API Number: 071-07901 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 292646 Type: PIT API Number: - Status: AC Insp. Status: AC

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID: 292646      Lat: 37.115240      Long: -104.952900

Reference Point: SE      Other: \_\_\_\_\_      Length: 80      Width: 30

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: None      Fencing Condition: \_\_\_\_\_

Comment:

Corrective

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment: NONE

Corrective

Date: \_\_\_\_\_

Anchor Trench Present: NO      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment:

Corrective

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695105015	INSP PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5562443">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5562443</a>