

Inspection Photos

Cosslet A 9 Flowline Excavation Access Road/Flowline Header



Photo 1 – Stained soil at header



Photo 2 – Stained soil along flowline path

Inspection Photos

Cosslet A 9 Flowline Excavation Access Road/Flowline Header



Photo 3 – Stained soil along flowline path.



Photo 4 – Two locations of stained soil

Inspection Photos

Cosslet A 9 Flowline Excavation Access Road/Flowline Header



Photo 5 – Map showing location of stained soil