

Inspection Photos
Operator: Simcoe
API: 067-05244
Date: 10/22/2021



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing with western wheatgrass, ssand dropseed, and rubber rabbitbrush.



Photo 3. View of musk thistles in post-flowering condition, in the southeastern project area. Approximately 150 individuals observed.



Photo 4. View of the reference area comprised of irrigated grass field with grasses such as smooth brome, orchard grass, and foxtail barley, as well as scattered sagebrush and wetland vegetation such as cattails.