

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	barbwire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Ancillary equipment	# 1	Electric panel, meter box and transformers			
Prime Mover	# 1	electric motor			
Pump Jack	# 1				
Bradenhead	# 1	appears to be plumbed to surface			

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

Comment:	See related inspection Doc #699302433 for information concerning shared facilities and equipment.		
----------	---	--	--

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241242 Type: WELL API Number: 123-09030 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/03/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: appears to be plumbed to surface

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 10/25/2021 at approximately 1420 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Follow up inspection to Doc # 699304356 Teets-Perrin 4 at API #05-123-09030 in Weld County Colorado. While there, I observed well site, PR at the time of inspection. During this inspection the following possible compliance issue has been addressed: Rule 606 housekeeping: weeds overgrown along access and throughout wellsite have been cut. See attached photos. Location is wet, weather is clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	10/25/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304419	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5563660