

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/26/2021

Submitted Date:

10/26/2021

Document Number:

700703423

FIELD INSPECTION FORM

 Loc ID 398836 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:
 OGCC Operator Number: 100264
 Name of Operator: XTO ENERGY INC
 Address: 110 W 7TH STREET
 City: FORT WORTH State: TX Zip: 76102
Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301740	WELL	PR	07/17/2009	GW	103-11465	PICEANCE CREEK UNIT 297-11C5	PR
301741	WELL	PR	05/29/2012	GW	103-11466	PICEANCE CREEK UNIT 297-11C4	PR
301742	WELL	PR	08/01/2021	GW	103-11467	Piceance Creek Unit 297-11C8	PR
301743	WELL	PR	08/01/2021	GW	103-11468	PICEANCE CREEK UNIT 297-11C1	PR
301744	WELL	PR	09/08/2010	GW	103-11469	Piceance Creek Unit 297-11C7	PR
301745	WELL	PR	09/18/2010	GW	103-11470	PICEANCE CREEK UNIT 297-11C2	PR
301746	WELL	PR	07/17/2009	GW	103-11471	Piceance Creek Unit 297-11C9	PR
301747	WELL	PR	07/17/2009	GW	103-11472	PICEANCE CREEK UNIT 297-11C6	PR
301748	WELL	PR	07/17/2009	GW	103-11473	PICEANCE CREEK UNIT 297-11C3	PR

General Comment:

COGCC Inspection Report Summary

On Monday 10/25/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus PCU 297-11C, at Location # 398836 in Rio Blanco county Colorado.

While there, I observed well was shut in. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Chemical tanks containment are full of fluid
2. Cut slope shows signs if lack of stabilization/erosion

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	location entrance		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks in plastic containments. Chemical tanks containment are full of fluid		
Corrective Action:	Provide sufficient containment space to contain possible spill		Date: 11/05/2021
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 9		
Comment:			
Corrective Action:			Date:
Type: Horizontal Separator	# 1		

Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	301740	Type:	WELL	API Number:	103-11465	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	301741	Type:	WELL	API Number:	103-11466	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	301742	Type:	WELL	API Number:	103-11467	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	301743	Type:	WELL	API Number:	103-11468	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	301744	Type:	WELL	API Number:	103-11469	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	301745	Type:	WELL	API Number:	103-11470	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	301746	Type:	WELL	API Number:	103-11471	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	301747	Type:	WELL	API Number:	103-11472	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				

Facility ID: 301748 Type: WELL API Number: 103-11473 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				

Comment: [1. Cut slope shows signs if lack of stabilization/erosion](#)

Corrective Action: [Install or repair required BMPs](#)

Date: 12/31/2021

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	302059	1942580	
	302059	1942580	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703427	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564074