

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/26/2021

Submitted Date:

10/26/2021

Document Number:

700703424

**FIELD INSPECTION FORM**

Loc ID 335796 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

16 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273860	WELL	PR	07/01/2021	GW	103-10499	PICEANCE CREEK UNIT T87X-3G	PR
273861	WELL	SI	08/01/2021	GW	103-10500	PICEANCE CREEK UNIT T87X-3G1	SI
273862	WELL	PR	11/01/2020	GW	103-10501	PICEANCE CREEK UNIT T87X-3G-2	PR
273863	WELL	PR	10/01/2019	GW	103-10502	PICEANCE CREEK UNIT T87X-3G-3	PR
273864	WELL	SI	08/01/2021	GW	103-10503	PICEANCE CREEK UNIT T87X-3G4	SI
283793	WELL	PR	07/01/2021	GW	103-10718	PICEANCE CREEK UNIT T87X-3G7	PR
283794	WELL	PR	03/01/2021	GW	103-10719	PICEANCE CREEK UNIT T87X-3G5	PR
283795	WELL	PR	06/08/2012	GW	103-10720	PICEANCE CREEK UNIT T87X-3G6	PR
283799	WELL	PR	04/01/2021	GW	103-10721	PICEANCE CREEK UNIT T87X-3G8	PR

**General Comment:**

COGCC Inspection Report Summary

On Monday 10/25/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus PCU T87X-3G, at Location # 335796 in Rio Blanco county Colorado.

While there, I observed well was shut in. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Random debris
2. Lack of battery signage
3. Fill slope shows signs of erosion

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

## Location

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Comply with rule 605.e	Date:	01/26/2022
Type	OTHER		
Comment:	Location entrance		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	911	
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	11/05/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 2		
Comment:	chemical tanks in plastic containments		
Corrective Action:		Date:	

Type: Plunger Lift	# 9		
Comment:			
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 9		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities				
Facility ID: 273860	Type: WELL	API Number: 103-10499	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing				
Corrective Action:		Date:		
Facility ID: 273861	Type: WELL	API Number: 103-10500	Status: SI	Insp. Status: SI
<b>Idle Well</b>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned    Reminder: _____				
Comment: Last produced 7/2021				
Corrective Action:		Date: _____		
Facility ID: 273862	Type: WELL	API Number: 103-10501	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing				
Corrective Action:		Date:		
Facility ID: 273863	Type: WELL	API Number: 103-10502	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing				
Corrective Action:		Date:		
Facility ID: 273864	Type: WELL	API Number: 103-10503	Status: SI	Insp. Status: SI
<b>Idle Well</b>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned    Reminder: _____				
Comment: Last produced 7/2021				
Corrective Action:		Date: _____		
Facility ID: 283793	Type: WELL	API Number: 103-10718	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing				
Corrective Action:		Date:		
Facility ID: 283794	Type: WELL	API Number: 103-10719	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing				
Corrective Action:		Date:		
Facility ID: 283795	Type: WELL	API Number: 103-10720	Status: PR	Insp. Status: PR

<b><u>Producing Well</u></b>			
Comment:	Producing		
Corrective Action:		Date:	
Facility ID:	283799	Type:	WELL
API Number:	103-10721	Status:	PR
Insp. Status:	PR		
<b><u>Producing Well</u></b>			
Comment:	Producing		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						

Comment: 1. Fill slope shows signs of erosion

Corrective Action: Install or repair required BMPs

Date: 12/31/2021

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703428	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564075">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564075</a>