

Inspection Photos

API: 125-06481

Operator: PETRON DEVELOPMENT COMPANY

Inspection Date: 10/25/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 125-06481 | Date: 10/25/2021

Inspection Photos



Photo 1. Facing east at the well site. This area at the well site has not re-established a uniform crop cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06481 | Date: 10/25/2021

Inspection Photos



Photo 2. Facing east. The red arrow points to 4.5 ft. shovel for scale. This area of the well site has insufficient crop cover which is approximately 20'x15' in size.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06481 | Date: 10/25/2021

Inspection Photos



Photo 3. Facing west. The red arrow points to 4.5 ft. shovel for scale. This area of the well site has insufficient crop cover which is approximately 20'x15' in size.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06481 | Date: 10/25/2021

Inspection Photos



Photo 4. Facing east toward the surrounding undisturbed crop which has uniform crop cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06481 | Date: 10/25/2021

Inspection Photos



Photo 5. Aerial image shows the area at the well site which has insufficient crop cover shown by the light area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06481 | Date: 10/25/2021