

## Inspection Photos

Location Name: UPRR 23 PAN AM D 2

Location ID: 319939



**Pic 1 pumping unit motor, stained soil/mechanical issue**



**Pic 2 Pumping unit stained soil next to wellhead**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: UPRR 23 PAN AM D 2

Location ID: 319939

Oct 22, 2021 at 3:55:28 PM  
39.936921,-104.582262  
Hudson CO 80642  
United States  
COGCC



**Pic 3 ECD used to Burn flare gas on location routed from gas meter run on location**

Oct 22, 2021 at 3:55:14 PM  
39.936923,-104.582385  
Hudson CO 80642  
United States  
COGCC



**Pic 4 tanks**