

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/26/2021

Submitted Date:

10/26/2021

Document Number:

699503283

FIELD INSPECTION FORM

Loc ID 319939 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Deranleau, Greg		greg.deranleau@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
,		dnr_cogccenforcement@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201948	WELL	PR	02/01/2021	OW	001-07352	UPRR 23 PAN AM D 2	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil by wellhead, from recent workover activities, stained soil by pumping unit motor.		
Corrective Action:	Comply with COGCC housekeeping rules.	Date:	11/26/2021
Type	OTHER		
Comment:	Venting / flaring was observed on this site. This site was part of the Third Creek pipeline shutdown. Gas meter run was removed, and replaced with a gas meter run that is connected to 3 ECD's that burn gas that is produced by this well.		
Corrective Action:	Close well to atmosphere as directed by Rule 434.b.(1)	Date:	10/28/2021

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Orange fencing around third creek abandoned pipeline.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Gas meter run automation		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:		Date:	

Type: Emission Control Device	# 3		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 201948 Type: WELL API Number: 001-07352 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 06/10/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Annual bradenhead test is not current. Contact COGCC engineering. Provide monthly monitoring data. 11/05/2021

Corrective Action: Comply with COGCC annual bradenhead testing rules. Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 10/22/21 at approximately 1600 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name-</p> <p>Company Name-</p> <p>API- 05-</p> <p>In Weld/Adams County Colorado.</p> <p>While there, I observed PR well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Venting / flaring was observed on this site. This site was part of the Third Creek pipeline shutdown. Gas meter run was removed, and replaced with a gas meter run that is connected to 3 ECD's that burn gas that is produced by this well.</p> <p>Close well to atmosphere as directed by Rule 434.b.(1) 10/28/21</p> <p>Stained soil by wellhead, from recent workover activities, stained soil by pumping unit motor.</p> <p>Comply with COGCC housekeeping rules. 11/26/21</p> <p>Annual bradenhead test is not current. Contact COGCC engineering. Provide monthly monitoring data.</p> <p>Comply with COGCC annual bradenhead testing rules. 11/5/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	10/26/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503284	Inspection Pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564280
699503285	Inspection video.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564281