

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2021

Submitted Date:

10/26/2021

Document Number:

700703432

FIELD INSPECTION FORM

Loc ID 335895 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285539	WELL	PR	08/01/2012	GW	103-10809	PICEANCE CREEK UNIT 297-15A1	PR
285540	WELL	PR	09/01/2012	GW	103-10810	PICEANCE CREEK UNIT 297-15A2	PR
285541	WELL	PR	07/17/2009	GW	103-10811	PICEANCE CREEK UNIT 297-15A3	PR
285542	WELL	PR	11/01/2019	GW	103-10812	PICEANCE CREEK UNIT 297-15A4	PR
285543	WELL	PR	07/01/2021	GW	103-10813	PICEANCE CREEK UNIT 297-15A5	PR
285544	WELL	PR	02/01/2016	GW	103-10814	PICEANCE CREEK UNIT 297-15A6	PR
285545	WELL	PR	06/01/2017	GW	103-10815	PICEANCE CREEK UNIT 297-15A7	PR
285546	WELL	PR	01/01/2021	GW	103-10816	PICEANCE CREEK UNIT 297-15A8	PR
285547	WELL	PR	09/01/2017	GW	103-10817	PICEANCE CREEK UNIT 297-15A9	PR

General Comment:

COGCC Inspection Report Summary

On Monday 10/25/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus PCU 297-15A, at Location # 335895 in Rio Blanco county Colorado.

While there, I observed well was shut in. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Chemical tank containments are full of fluid
2. Two dead men are not marked properly

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Location entrance		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	Two dead men are not marked properly		
Corrective Action:	Mark or remove dead men	Date:	11/26/2021
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 2		
Comment:	Chemical tanks in plastic containments. Chemical tank containments are full of fluid		
Corrective Action:	Provide sufficient containment space to contain possible spill		Date: 11/05/2021
Type: Bradenhead	# 9		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities						
Facility ID:	285539	Type:	WELL	API Number: 103-10809	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	285540	Type:	WELL	API Number: 103-10810	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	285541	Type:	WELL	API Number: 103-10811	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	285542	Type:	WELL	API Number: 103-10812	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	285543	Type:	WELL	API Number: 103-10813	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	285544	Type:	WELL	API Number: 103-10814	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	285545	Type:	WELL	API Number: 103-10815	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	285546	Type:	WELL	API Number: 103-10816	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:

Facility ID:	285547	Type:	WELL	API Number:	103-10817	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	284544	1433382	
	284544	1433382	

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703437	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564696