

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/20/2021

Submitted Date:

10/20/2021

Document Number:

700703400

FIELD INSPECTION FORMLoc ID 336007 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Thomson, Bud		BLThomps@BLM.gov	
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299793	WELL	PR	06/01/2013	GW	103-11420	FREEDOM UNIT 197-33B7	PR
299794	WELL	PR	06/01/2013	GW	103-11421	FREEDOM UNIT 197-33B8	PR
299795	WELL	PR	06/01/2013	GW	103-11422	FREEDOM UNIT 197-33B9	PR
299796	WELL	PR	06/01/2013	GW	103-11423	FREEDOM UNIT 197-33B10	PR
299797	WELL	PR	06/01/2013	GW	103-11424	FREEDOM UNIT 197-33B6	PR
299798	WELL	PR	06/01/2013	GW	103-11425	FREEDOM UNIT 197-33B5	PR
299799	WELL	PR	06/01/2013	GW	103-11426	FREEDOM UNIT 197-33B4	PR
299800	WELL	PR	08/01/2021	GW	103-11427	FREEDOM UNIT 197-33B2	PR
299801	WELL	PR	01/01/2017	GW	103-11428	FREEDOM UNIT 197-33B1	PR
300296	WELL	PR	06/01/2013	GW	103-11433	FREEDOM UNIT 197-33B3	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 10/18/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus Freedom unit 197-33B, at Location # 336007 in Rio Blanco county Colorado.

While there, I observed normal operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Cut slope shows signs of lack of stabilization

2. Random debris

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Entrance		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	10/29/2021

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks in plastic containments		
Corrective Action:		Date:	
Type: Bradenhead	# 10		
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 10		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID:	299793	Type:	WELL	API Number: 103-11420 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
Facility ID:	299794	Type:	WELL	API Number: 103-11421 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
Facility ID:	299795	Type:	WELL	API Number: 103-11422 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
Facility ID:	299796	Type:	WELL	API Number: 103-11423 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
Facility ID:	299797	Type:	WELL	API Number: 103-11424 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
Facility ID:	299798	Type:	WELL	API Number: 103-11425 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
Facility ID:	299799	Type:	WELL	API Number: 103-11426 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
Facility ID:	299800	Type:	WELL	API Number: 103-11427 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		

Facility ID:	299801	Type:	WELL	API Number:	103-11428	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID:	300296	Type:	WELL	API Number:	103-11433	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				

Comment: 1. Cut slope shows signs of lack of stabilization

Corrective Action: Install or repair required BMPs

Date: 12/24/2021

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402848164	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5560088
700703405	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5560082