

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2021

Submitted Date:

10/27/2021

Document Number:

696203307

**FIELD INSPECTION FORM**Loc ID 311604 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, "		COGCC.inspections@caerus oilandgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
311604	LOCATION	AC			-	GL-67S93W 18SWSE	RI

**General Comment:**

On 10/25/2021, Reclamation Specialist Trujillo conducted a stormwater inspection at Caerus Piceance's GL-67S93W 18SWSE location in Garfield County, Colorado.

The following compliance issues were observed during this inspection:  
1002.f: Stormwater

Refer to inspection #696203197 for corrective actions regarding unused equipment, noxious weeds, bird protectors and fence maintenance.

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #696203197 provided notice to Caerus that control measures to stabilize the location, and to mitigate tracking and offsite sediment transport were showing signs of degradation. Inspection directed Caerus to monitor and manage site for stormwater, and to ensure BMPs are maintained.

It was observed in this inspection that control measures to stabilize the production areas of the Location, and to mitigate tracking and offsite sediment transport have not been maintained in proper functioning condition, and are in disrepair.

The date of inspection is being provided as the CA date, as Caerus was provided prior notice of the imminent failure of their control measures.

Corrective Action: **Comply with Rule 1002.f**

Date: 10/25/2021

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696203308	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5565383">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5565383</a>