

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	fabricated round stock and hog wire		
Corrective Action:		Date:	

Equipment:

Type	Area	Volume	corrective date
Type: Bradenhead		# 1	
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack		# 1	
Comment:			
Corrective Action:		Date:	
Type: Prime Mover		# 1	
Comment:	electric motor		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241390 Type: WELL API Number: 123-09179 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 09/30/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 10/27/2021 at approximately 1305 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Follow up inspection to Doc #699303812. Cleveland #7 at API #05-123-09179 in Weld County Colorado. While there, I observed a wellsite, SI at time of inspection. During this inspection the following possible compliance issues have been addressed: 603.f Housekeeping: Tumble weeds/Weeds around location, WH & equipment have been cut and removed. 603.f Housekeeping: Unused equipment on location, Pump jack has been assembled over the WH and appears to be in the process of being brought back to PR status. See attached photos. Location: dry, Weather: clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	10/27/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304425	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5565765