

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/21/2021

Submitted Date:

10/21/2021

Document Number:

695105004

FIELD INSPECTION FORMLoc ID 307463 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Duran, Alicia		alicia.duran@state.co.us	
,		dnr_cogccengineering@state.co.us	
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217697	WELL	SI	12/01/2019	GW	071-06476	LINDA 12-19	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead

1

Comment: PHOTO 3: Bradenhead inaccessible or not visible.

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).

Date: 11/21/2021

Type: Ancillary equipment

1

Comment: TELEMETRY EQUIPMENT

Corrective Action:

Date:

Type: Deadman # & Marked

5

Comment: ALL HAVE MARKERS

Corrective Action:

Date:

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

Corrective Action:

Date:

Type: Progressive Cavity

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected FacilitiesFacility ID: 217697 Type: WELL API Number: 071-06476 Status: SI Insp. Status: SI**Workover**

Comment: OPERATOR PERFORMED MIT.
TOP OF PERFS @ 949', RBP SET @ 912'.
INITIAL CSG PSI. 314
5 MIN. 313.5 PSI,
10 MIN. 313.5 PSI
FINAL 313.5 PSI. .5 PSI DROP IN PRESSURE DURING TEST WITH 0 PSI DROP IN
LAST 5 MIN.
BRADENHEAD NOT PLUMBED TO SURFACE

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 113649Lat: 37.159291Long: -104.720917Reference Point: SE

Other: _____

Length: 80Width: 30**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective

Date:

Fencing:Fencing Type: None

Fencing Condition:

Comment:

Corrective

Date:

Netting:

Netting Type:

Netting Condition:

Comment: NONE

Corrective

Date:

Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective

Date:

COGCC Comments

Comment	User	Date
THIS IS A MIT AND FOLLOW UP OF INSP. DOC #695104273, CA HAS NOT BEEN ADDRESSED. THIS IS THE SECOND NOTICE OF NO ACCESS TO THE BRHD.	beardslt	10/21/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402849802	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5561379
695105005	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5561368