

TEP
RGU 323-33-198
Location # 335719



location



location

TEP
RGU 323-33-198
Location # 335719



Lack of glycol vessel labeling



location/lack of battery signage



TEP
RGU 323-33-198
Location # 335719



location



Lack of stabilization/erosion/BMP's failing



TEP
RGU 323-33-198
Location # 335719



Lack of stabilization/erosion/BMP's failing



Lack of stabilization/erosion/BMP's failing



TEP
RGU 323-33-198
Location # 335719



Lack of stabilization/erosion/BMP's failing



Lack of stabilization/erosion/BMP's failing



TEP
RGU 323-33-198
Location # 335719



Lack of stabilization/erosion/BMP's failing



Lack of stabilization/erosion/BMP's failing



TEP
RGU 323-33-198
Location # 335719



Lack of stabilization/erosion/BMP's failing



location



TEP
RGU 323-33-198
Location # 335719



Chemical tank containment is full of fluid



Load out line missing cap/bull plug

TEP
RGU 323-33-198
Location # 335719



Load out line missing cap/bull plug



Tank label missing information

TEP
RGU 323-33-198
Location # 335719



Leaking load out line with out cap/bull plug and staining



Leaking load out line with out cap/bull plug and staining

TEP
RGU 323-33-198
Location # 335719



Leaking load out line with out cap/bull plug and staining



Leaking load out line with out cap/bull plug and staining



TEP
RGU 323-33-198
Location # 335719



Missing load out cap/bull plug and cap for burner



Debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources