

Inspection Photos
Operator: Simcoe
API: 067-07849
Date: 10/27/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with grasses, largely in a grazed condition.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of the reference area comprised of irrigated grass field with grasses such as meadow brome, orchard grass, perennial rygrass, as well as riparian shrubs and trees such as cottonwoods and willows.