

Inspection Photos

API: 061-05143

Operator: WESTERN OPERATING COMPANY

Inspection Date: 10/27/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-05143 | Date: 10/27/2021

Inspection Photos



Photo 1. Facing northwest toward the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05143 | Date: 10/27/2021

Inspection Photos



Photo 2. There is animal burrows compromising the berm around the tank battery. The secondary containment is not sufficiently impervious to contain spill. Earthen berms need to be repaired and compacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05143 | Date: 10/27/2021

Inspection Photos



Photo 3. Facing south approximately 180' downhill from the tank battery. A former spill had occurred in this area as shown by bare soils. It appears manure was spread throughout this area. The soils in this area need to be sampled to determine impacted soil properties.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05143 | Date: 10/27/2021

Inspection Photos



Photo 4. Facing southeast approximately 180' downhill from the tank battery. A former spill had occurred in this area as shown by bare soils. The soils in this area need to be sampled to determine impacted soil properties per 915.b.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05143 | Date: 10/27/2021

Inspection Photos



Photo 5. Facing southeast downhill from the tank battery. A former spill had occurred in this area as shown by bare soils. The soils in this area need to be sampled to determine impacted soil properties per 915.b.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05143 | Date: 10/27/2021

Inspection Photos



Photo 6. Facing northeast toward the area where manure was spread. The application of uncomposted manure will likely bring in undesirable weeds into this area. This location will need to be monitored for weed management.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05143 | Date: 10/27/2021

Inspection Photos



Photo 7. Facing toward the well site which is approximately 800' northwest of the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05143 | Date: 10/27/2021