

Inspection Photos
Location Name: Carl A Miller A 4
Location ID: 318365



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Carl A Miller A 4
Location ID: 318365



Photo 3 Access Rd.



Photo 4 ancillary equipment

Inspection Photos
Location Name: Carl A Miller A 4
Location ID: 318365



Photo 5 plug has been tightened and leak stopped.



Photo 6 Stained soil between pump jack concrete slabs