

Inspection Photos
Location Name: Marie Gerhardt B2
Location ID: 317863



Photo 1 WH sign



Photo 2 Stained soil and weeds have been removed from around WH

Inspection Photos
Location Name: Marie Gerhardt B2
Location ID: 317863



Photo 3 Pump Jack

Photo 4 Ancillary equipment

Inspection Photos
Location Name: Marie Gerhardt B2
Location ID: 317863



Photo 5 TB sign

Photo 6 TB

Inspection Photos
Location Name: Marie Gerhardt B2
Location ID: 317863



Photo 7 ECD and Horiz. Heated Sep. dead weeds inside fencing

Photo 8 dead weeds inside fencing by Horiz. Heated Sep.

Inspection Photos
Location Name: Marie Gerhardt B2
Location ID: 317863



Colorado Oil & Gas Conservation Commission



Colorado Oil & Gas Conservation Commission

Photo 9 dead weeds inside fencing by ECD

Photo 10 dead weeds by flow line manifold.

Inspection Photos
Location Name: Marie Gerhardt B2
Location ID: 317863



Colorado Oil & Gas Conservation Commission



Colorado Oil & Gas Conservation Commission

Photo 11 dead weeds and stained soil by flow line manifold

Photo 12 dead weeds by flow line manifold and on TB berm

Inspection Photos
Location Name: Marie Gerhardt B2
Location ID: 317863



Colorado Oil & Gas Conservation Commission



Colorado Oil & Gas Conservation Commission

Photo 13 dead weeds inside TB berm

Photo 14 dead weeds by Gas Meter Run inside TB berm

Inspection Photos
Location Name: Marie Gerhardt B2
Location ID: 317863



Colorado Oil & Gas Conservation Commission



Colorado Oil & Gas Conservation Commission

Photo 15 stained soil by Crude tank flow line

Photo 16 stained soil by Crude tank

Inspection Photos
Location Name: Marie Gerhardt B2
Location ID: 317863



Colorado Oil & Gas Conservation Commission



Colorado Oil & Gas Conservation Commission

Photo 17 Gas Meter Run

Photo 18 Card in meter box indicates that calibration is not current