

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/21/2021

Submitted Date:

10/22/2021

Document Number:

700300290

FIELD INSPECTION FORM

Loc ID 320902 Inspector Name: LABOWSKIE, STEVE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69805
Name of Operator: PETROX RESOURCES INC
Address: 12600 W COLFAX AVENUE #C-440
City: LAKEWOOD State: CO Zip: 80215

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
CLARK, RYAN	303-80303998	ryan@petrox-resources.com	ALL Inspections
Clark, Mike	970-878-5594	mike.petrox@gmail.com	All Inspections
Nystrom, Dusty	(505) 330-1328/ (719) 529-0682	nystrow@yahoo.com	Field Representative

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292015	WELL	PR	03/01/2021	GW	007-06235	FOSSET GULCH UNIT 9U 4	PR

General Comment:

Inspection to confirm noise compliance and gas meter calibration record. Inspection supervisor arrived location shortly before operator. Operator in process of exchanging motor for pumping unit. Appears cattle had knock down panel fencing around idled unit and knock over lube oil tank resulting in a release on ground. Operator began clean up and response and per phone conversation will have clean up completed 10/22/2021.

The inspection does not address corrective actions from reclamation inspection doc#6939003670.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER
Comment:	cattle knocked over lube oil tank resulting in release of lubrication oil (~2 qt), operator on site and began response and clean up immediately
Corrective Action:	<input type="text"/>

Date: _____

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PUMP JACK

Comment: cattle tore down panel fencing

Corrective Action: Repair fencing to appropriate level to resist livestock and wildlife in area

Date: 10/29/2021

Equipment:

corrective date

Type: Gas Meter Run # 1

Comment: Current calibration record now displayed, CA from FIR doc# 700300278 satisfactorily performed

Corrective Action:

Date: _____

Venting:

Yes/No NO

Comment:

Corrective Action:

Date: _____

Flaring:

Type	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/>

Date: _____

Inspected Facilities

Facility ID: 292015 Type: WELL API Number: 007-06235 Status: PR Insp. Status: PR

Complaint

Comment: Operator changing out motor assembly on pumping unit due to bearing going out. Operator stated noise levels should be reduced with different equipment. Staff will confirm compliance to COGCC rules when unit reactivated. Operator should also monitor and coordinate with FS/USFW on expectations for long term measurements, monitoring and mitigation

Corrective Action:

Date:

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well idled while repairs made on pumping unit

Corrective Action:

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402850301	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5561786
700300291	current meter calibration record	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5561784
700300292	lube oil tank knock over by cattle	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5561785