

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2021

Submitted Date:

10/29/2021

Document Number:

688801004

FIELD INSPECTION FORM

 Loc ID 320854 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 900Name of Operator: ALAMOSA DRILLING INCAddress: 8150 N. CENTRAL EXPY - STE 750City: DALLAS State: TX Zip: 75205-**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments4 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
Mercer, Lauren		lauren.mercer@coag.gov	
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	All Inspections
Schultz, Scott		scott.schultz@coag.gov	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205242	WELL	PR	06/01/2021	OW	007-06120	CHAVEZ 1	EI
457801	SPILL OR RELEASE	AC	10/05/2018		-	Chavez 1	EI

General Comment:

On October 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Chavez #1. For the most recent field inspection report of this facility, please refer to document #688800012.

Location			
Lease Road:			
	Type Access		
comment:			
Corrective ActionL		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
	Type BATTERY		
Comment:	API numbers of contributing wells have been added to battery sign.		
Corrective Action:		Date:	
	Type WELLHEAD		
Comment:	Additional information required by Inspection Document #688800012 has been added to well head sign.		
Corrective Action:		Date:	
	Type TANK LABELS/PLACARDS		
Comment:	AST is labeled with NFPA placard, contents, and capacity.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Emergency contact information has been added to well head sign.		
Corrective Action:		Date:	_____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Flatbed gooseneck trailer stored on location. Roll of chain link fencing stored near pump jack.		
Corrective Action:	Comply with Rule 606	Date:	11/28/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	Wellhead and surrounding area is wet and stained with oil. Absorbent granules have been spread on top of impacted soil.		
Corrective Action:	The Operator will clean up impacts and collect confirmation samples to ensure compliance with Table 915-1, per Rule 912.a.(3).		Date: 11/28/2021
In Containment: No			
Comment:	<div style="border: 1px solid black; padding: 5px;"> Per Rule 912.d.(1): Operators will determine and document the cause of a Grade 1 Gas Leak or Spill or Release of E&P Waste or produced Fluids. After identifying the cause, Operators will implement measures to prevent Spills or Releases due to similar causes in the future, and document all changes made. A possible solution to this reoccurring issue would be to have the Operator install a containment system for the stuffing box. </div>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Post and wire fencing around well head and pump jack.		

Corrective Action:	Date:
--------------------	-------

Equipment:		corrective date
Type: Prime Mover	# 1	
Comment: Electric motor.		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Other	# 1	
Comment: Supply shed.		
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		37.018081,-106.875100
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
007-06136
007-06120

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
------	--

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 205242 Type: WELL API Number: 007-06120 Status: PR Insp. Status: EI

Facility ID: 457801 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Comment	User	Date
<p>On October 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Chavez #1. For the most recent field inspection report of this facility, please refer to document #688800012.</p> <p>API numbers of contributing wells have been added to the tank battery sign.</p> <p>Additional information required by Inspection Document #688800012 has been added to well head sign.</p> <p>Flatbed gooseneck trailer stored on location. Roll of chain link fencing stored near pump jack.</p> <p>Wellhead and surrounding area is wet and stained with oil. Absorbent granules have been spread on top of oil impacted soil.</p> <p>The Operator will clean up impacts and collect confirmation samples to ensure compliance with Table 915-1, per Rule 912.a.(3).</p> <p>Open topped container with oily contents observed near supply shed.</p> <p>Per Rule 912.d.(1): Operators will determine and document the cause of a Grade 1 Gas Leak or Spill or Release of E&P Waste or produced Fluids. After identifying the cause, Operators will implement measures to prevent Spills or Releases due to similar causes in the future, and document all changes made.</p> <p>A possible solution to this reoccurring issue would be to have the Operator install a containment system for the stuffing box.</p>	hughesjo	10/29/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801005	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5567968