

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2021

Submitted Date:

10/29/2021

Document Number:

688801006**FIELD INSPECTION FORM**Loc ID 320860 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 900Name of Operator: ALAMOSA DRILLING INCAddress: 8150 N. CENTRAL EXPY - STE 750City: DALLAS State: TX Zip: 75205-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	All Inspections
Mercer, Lauren		lauren.mercer@coag.gov	
Schultz, Scott		scott.schultz@coag.gov	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205258	WELL	PR	06/01/2021	OW	007-06136	CHAVEZ 2	EI

General Comment:

On October 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Chavez #2. For the most recent field inspection report of this facility, please refer to document #688800889.

Location					
Lease Road:					
	Type	Access			
	comment:				
	Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
	Type	WELLHEAD			
	Comment:	Additional information required by Inspection Document #688800889 has been posted on well head sign.			
	Corrective Action:			Date:	
	Type	BATTERY			
	Comment:	API numbers of contributing wells have been added to the tank battery sign.			
	Corrective Action:			Date:	
Emergency Contact Number:					
	Comment:	Emergency contact information has been added to well head sign.			
	Corrective Action:			Date:	
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
	Comment:				
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
	Type	PUMP JACK			
	Comment:	Post and wire fencing around pump jack and well head.			
	Corrective Action:			Date:	
Equipment:					
				corrective date	
Type: Flow Line	# 1				
	Comment:				
	Corrective Action:			Date:	
Type: Pump Jack	# 1				
	Comment:	Electric prime mover has previously been removed.			
	Corrective Action:			Date:	
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		37.018064,-106.875094
	Comment:	Shared tank battery with Chavez #1.			
	Corrective Action:			Date:	
Paint					

Inspector Name: Hughes, Jim

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above

AirsID

API Number
007-06120
007-06136

API Number	AirsID
------------	--------

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On October 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Chavez #2. For the most recent field inspection report of this facility, please refer to document #688800889.</p> <p>Additional information required by Inspection Document #688800889 has been posted on well head sign.</p> <p>API numbers of contributing wells have been added to the tank battery sign.</p> <p>Emergency contact information has been added to well head sign.</p> <p>Pump jack does not have prime mover.</p>	hughesjo	10/29/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801007	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568040