



# Final Reclamation Inspection Form

Site: Aloha Mula #16 Jetted  
 Date: 06/22/2021  
 Conditions: 100 F sunny

Inspector: Brian Podobnik

Land Use: Range  
 If Crop: \_\_\_\_\_  
 If other land use: \_\_\_\_\_

Access Road in Use: No  
 If yes, in use by: \_\_\_\_\_  
 Located on active pad? No  
 Located in interim rec of active pad? No

TB inspected: No TB status: NA

TB name and/or #: NA

	Present (Y/N)	Notes
Debris or Trash on Site	No	
Equipment on Site (culverts, pipes, etc.)	No	
Livestock Grazing/Disturbances	No	
Vehicle Disturbances	No	
Wildlife Disturbances	No	
Seed Germination	Yes	
Plants Vigorous	Yes	
Uniform growth (height and density)	Yes	Minimal areas of thin or sparse growth
Undesirable Species (non-noxious weeds)	Yes	Summer cypress and slender russian thistle
Noxious Weeds	No	
Stormwater Issues (erosion)	No	
Subsidence (depressions, sinking)	No	
Site Re-contoured Properly	Yes	
Road Re-contoured Properly	Yes	
Road base/gravel on site (road or pad)	No	
Compaction (On-Site)	NA	2" to 3" in @ 300 psi
Compaction (Off-Site)	NA	2" to 3" in @ 300 psi
Reclamation area fenced	Yes	

Plants Observed	On Site	Off Site	Desirable
Common Pepperweed	Yes	Yes	Yes
Big Needlegrass	Yes	Yes	Yes
Pinyon Goosefoot	Yes	Yes	Yes
Prairie Sunflower	Yes	Yes	Yes
Field Sagewort	Yes	Yes	Yes
Idaho Fescue	Yes	Yes	Yes
Prickly Poppy	Yes	Yes	Yes
Slender Russian Thistle	Yes	Yes	No
Purple Threeawn	Yes	Yes	Yes
Soapweed Yucca	Yes	Yes	Yes
Summer Cypress	Yes	Yes	No

Recommendations:	
Seeding	No
Weed Control	No
Erosion Control	No
Compaction Alleviation	No
Other:	

Other Comments/Observations: Site was recently mowed. Site appears to have reached 70% uniform vegetation cover.

Recommend for Final Form 4? Yes



# PHOTOGRAPHIC LOG



**Photograph 1:** North facing photograph.



**Photograph 2:** East facing photograph.



**Photograph 3:** South facing photograph.



**Photograph 4:** West facing photograph.

## PHOTOGRAPHIC LOG



**Photograph 5:** Overview photograph.