

# Inspection Photos

API: 043-06219

Operator: AUSCO PETROLEUM INC

Inspection Date: 10/27/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 043-06219 | Date: 10/27/2021

## Inspection Photos



**Photo 1.** Facing northwest along the access road. The check dams along the road have filled in with sediment and need to be maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/27/2021



## Inspection Photos



**Photo 2.** There are wattles along the access road that are filled in with sediment and not maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/27/2021



## Inspection Photos



**Photo 3.** Facing northeast toward the location. Unused equipment has not been removed and interim reclamation has not been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/27/2021



## Inspection Photos



**Photo 4.** Facing northeast at the location. There are 5 frac tanks staged that remain at east side of the location. The tanks have not been removed since previous inspection. Previous corrective actions have not been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/27/2021



## Inspection Photos



**Photo 5.** Facing north at the south corner of the location. There is erosion occurring from the disturbed pad site which is filling in the perimeter wattles. Previous corrective action has not been performed.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 043-06219 | Date: 10/27/2021



## Inspection Photos



**Photo 6.** Facing southwest behind the frac tanks. The wattles have filled in with sediment. Previous corrective action has not been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/27/2021



## Inspection Photos



**Photo 7.** Facing northeast at the location. Disturbed areas around the location have not been reclaimed and stabilized. There are undesirable weeds that have grown throughout disturbed areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/27/2021



## Inspection Photos



**Photo 8.** Facing southwest at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/27/2021



## Inspection Photos



**Photo 9.** There is an open trench at the location that has been excavated.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/27/2021



## Inspection Photos



**Photo 10.** The tanks at north side of the location are not properly labeled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/27/2021

## Inspection Photos



**Photo 11.** Facing southeast at the location and toward the production equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/27/2021



## Inspection Photos



**Photo 12.** Facing toward the topsoil pile. The topsoil piles are not stabilized and protected. Topsoil piles have not been replaced for interim reclamation. There are undesirable weeds throughout the stockpiles.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/27/2021



## Inspection Photos



**Photo 13.** Facing southeast toward the topsoil pile which are not maintained and protected from degradation and weed infestation. Previous corrective action has not been performed. The BMP's around the stockpile are not maintained.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 043-06219 | Date: 10/27/2021



## Inspection Photos



**Photo 14.** Facing northeast toward the location. The unused tanks need to be removed. Unused areas of the location need to be recontoured and reclaimed. Previous corrective actions have not been performed.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 043-06219 | Date: 10/27/2021