

# Inspection Photos

API: 05-017-07453

Operator: RESOURCE DEVELOPMENT

Inspection Date: 10/26/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/26/2021

## Inspection Photos



**Photo 1.** Facing west at the beginning of the access road. The wood posts still remain.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/26/2021

## Inspection Photos



**Photo 2.** Facing west along the former access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/26/2021

## Inspection Photos



**Photo 3.** View of vegetation along the road. There is areas with Field bindweed which is a noxious weed that needs to be controlled. Arrow points to the green colored bindweed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/26/2021

## Inspection Photos



**Photo 4.** Facing west toward the location. Vegetation has not adequately established and bare areas have compacted soils. It appears the soils were not cross ripped as required. This area needs to be decompacted and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/26/2021

## Inspection Photos



**Photo 5.** West side of the location facing east. There are rows of compacted soil where vegetation is sparse. This area has not adequately re-established to 80% reference area levels.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/26/2021

## Inspection Photos



**Photo 6.** Facing south at the location. The perennial vegetation has progressed more in areas of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/26/2021

## Inspection Photos



**Photo 7.** View of vegetation at the location. There is areas with Field bindweed which is a noxious weed that needs to be controlled. Arrow points to the green colored bindweed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/26/2021

## Inspection Photos



**Photo 8.** There is an area of subsidence at the location which is approximately 1-2ft. deep. Red arrow points to 5 ft. shovel placed in the area.  
Approx. Lat/Long:38.85031,-102.39605.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/26/2021

## Inspection Photos



**Photo 9.** There is another area of subsidence at the north side of the location which is approximately 3-4ft. deep. Red arrow points to 5 ft. shovel placed in the area. Approx. Lat/Long:38.85052,-102.39459.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/26/2021

## Inspection Photos



**Photo 10.** Facing north toward the undisturbed reference area which is mostly composed of Sideoats grama, Blue grama, and Sand dropseed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/26/2021