

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/28/2021

Submitted Date:

10/28/2021

Document Number:

701102111

FIELD INSPECTION FORM

Loc ID 314303 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 760 HORIZON DRIVE STE 400
City: GRAND JUNCTION State: CO Zip: 81506

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|-------------------------------------|
| Gas, UtahGasCorp | 970-693-6021 | inspections@utahgascorp.com | Inspection mail box |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 103945 | PIT | AC | 04/19/2021 | | - | BIG HORSE DRAW 1 | AC |
| 228280 | WELL | PR | 05/01/2018 | GW | 103-05106 | BIG HORSE DRAW 1 | PR |

General Comment:

[COGCC Routine Inspection Report Summary](#)

| Location | | | |
|--|------------|--------|-----------------|
| Lease Road: | | | |
| Type | Main | | |
| comment: | CR 116 | | |
| Corrective Action | L | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | 911 | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | PIT | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Bradenhead | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 103945 Type: PIT API Number: - Status: AC Insp. Status: AC

Facility ID: 228280 Type: WELL API Number: 103-05106 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|----------------------------|
| Compaction | | | | | | |
| | | Compaction | | | | |
| | | Culverts | | | | |
| | | | | Material Handling And Spill Prevention | | Methanol tote at gas meter |
| | | Gravel | | | | |

Comment: Water collecting at well.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: NO Pit ID: 103945 Lat: 39.833763 Long: -108.751126

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective

Date:

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective

Date:

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective

Date:

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 701102112 | Inspection 701102111 photo log | http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5569143 |