

Inspection Photos
Operator: Simcoe
API: 067-06544
Date: 10/27/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with grasses such as western wheatgrass, sand dropseed, and intermediate wheatgrass.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of kochia debris round project facilities, needing removal.



Photo 5. View of the reference area comprised of irrigated grass field with smooth brome, orchard grass, and mixed wheatgrasses.