

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/22/2021

Submitted Date:

10/22/2021

Document Number:

699503279

FIELD INSPECTION FORMLoc ID 319742 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10711

Name of Operator: PAINTED PEGASUS PETROLEUM LLC

Address: 16820 BARKER SPRINGS RD #521

City: HOUSTON State: TX Zip: 77084

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		JH@p3petro.com	
		jm@p3petro.com	
		khubbard@p3petro.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201214	WELL	SI	12/01/2019	OW	001-06617	UPRR-WAILES 1-1	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Wellhead sign needs to be re installed, At time of inspection wellhead sign was on the ground next to wellhead.

Corrective Action:

Date:

Good Housekeeping:

Type WEEDS

Comment: Weeds and debris on locaiton need to be removed.

Corrective Action: Comply with COGCC housekeeping rules.

Date: 12/30/2020

Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: 4' barb wire, needs to be repaired.

Corrective Action:

Date:

Type TANK BATTERY

Comment: 4' Barb wire

Corrective Action:

Date:

Equipment:

corrective date

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator # 1

Comment:

Corrective Action:

Date:

Type: Bradenhead # 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: Plunger lift automation

Corrective Action:

Date:

Type: Bird Protectors # 1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: Berms needs to be rebuilt around tank on north end of location next to separator, see pic 2,3				
Corrective Action: Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G.				Date: 11/06/2021

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 201214 Type: WELL API Number: 001-06617 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Well will require MIT if shut in past 12/1/21

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 05/19/2020

Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Annual bradenhead test is not current. Contact COGCC engineering. Provide monthly bradenhead monitoring data.

11/01/2021

Corrective Action: Comply with COGCC annual bradenhead tetsting rules

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 10/22/21 at approximately 1345 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- UPRR-WAILES 1-1</p> <p>Company Name- Painted Pegasus</p> <p>API- 05-001-06617</p> <p>In Adams County Colorado.</p> <p>While there, I observed SI well.</p> <p>This is a follow up inspection from document # 700900386 Corrective Actions are Delinquent</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds and debris on locaiton need to be removed.</p> <p>Comply with COGCC housekeeping rules. 12/30/21</p> <p>Berms needs to be rebuilt around tank on north end of location next to separator, see pic 2,3</p> <p>Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G. 11/6/21</p> <p>Annual bradenhead test is not current. Contact COGCC engineering. Provide monthly bradenhead monitoring data.</p> <p>Comply with COGCC annual bradenhead tetsting rules 11/1/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	10/22/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402853427	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564290
699503280	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564278