



**Location**

Overall Good:

Emergency Contact Number: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Venting / flaring was observed on this site. This site was part of the Third Creek pipeline shutdown. Gas meter run was removed, and replaced with a gas meter run that is connected to 3 ECD's that burn gas that is produced by this well.		
Corrective Action:	Close well to atmosphere as directed by Rule 434.b.(1)	Date:	10/28/2021
Type	OTHER		
Comment:	Stained soil by wellhead, from recent workover activities, stained soil by pumping unit motor.		
Corrective Action:	Comply with COGCC housekeeping rules.	Date:	11/26/2021

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Orange fencing around third creek abandoned pipeline.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 3		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Gas meter run automation		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 201948 Type: WELL API Number: 001-07352 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 06/10/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Annual bradenhead test is not current. Contact COGCC engineering. Provide monthly monitoring data.

11/05/2021

Corrective Action: Comply with COGCC annual bradenhead testing rules.

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On 10/22/21 at approximately 1600 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name-                      Company Name-                      API- 05-                      In Weld/Adams County Colorado.                      While there, I observed PR well                      During this inspection the following possible compliance issues were observed:                      Venting / flaring was observed on this site. This site was part of the Third Creek pipeline shutdown. Gas meter run was removed, and replaced with a gas meter run that is connected to 3 ECD's that burn gas that is produced by this well.                      Close well to atmosphere as directed by Rule 434.b.(1) 10/28/21                      Stained soil by wellhead, from recent workover activities, stained soil by pumping unit motor.                      Comply with COGCC housekeeping rules. 11/26/21                      Annual bradenhead test is not current. Contact COGCC engineering. Provide monthly monitoring data.                      Comply with COGCC annual bradenhead testing rules. 11/5/21                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	medinaj	10/26/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402853433	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564295">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564295</a>
699503284	Inspection Pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564280">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564280</a>
699503285	Inspection video.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564281">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564281</a>