

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/26/2021

Submitted Date:

10/26/2021

Document Number:

700703422

FIELD INSPECTION FORM

Loc ID 335712	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 100264 Name of Operator: XTO ENERGY INC Address: 110 W 7TH STREET City: FORT WORTH State: TX Zip: 76102				Findings: 15 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259652	WELL	SI	08/01/2021	GW	103-10112	PICEANCE CREEK UNIT T35X-11G	SI
274342	WELL	SI	08/01/2021	GW	103-10528	PICEANCE CREEK UNIT T35X-11G4	SI
274343	WELL	PR	05/04/2020	GW	103-10527	PICEANCE CREEK UNIT T35X-11G3	PR
274344	WELL	SI	08/01/2021	GW	103-10526	PICEANCE CREEK UNIT T35X-11G2	SI
274346	WELL	SI	06/01/2021	GW	103-10524	PICEANCE CREEK UNIT T35X-11GS	SI
279500	WELL	SI	08/01/2021	GW	103-10627	PICEANCE CREEK UNIT T35X-11G5	SI
279501	WELL	SI	03/01/2021	GW	103-10626	PICEANCE CREEK UNIT T35X-11G6	SI
279502	WELL	SI	04/01/2021	GW	103-10625	PICEANCE CREEK UNIT T35X-11G7	SI

General Comment:

COGCC Inspection Report Summary

On Monday 10/25/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus PCU T35X-11G, at Location # 335712 in Rio Blanco county Colorado.

While there, I observed well was shut in. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Lack of battery signage
2. Random debris
3. Fill slope erosion/sediment migration

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Entrance to location		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Comply with rule 605.e	Date:	01/26/2022

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	11/05/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 8		corrective date
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 3	
Comment:	Chemical tanks Two are in metal containments and One is in plastic containment	
Corrective Action:		Date:
Type: Bradenhead	# 8	
Comment:		
Corrective Action:		Date:
Type: Horizontal Separator	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 259652 Type: WELL API Number: 103-10112 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last produced 7/2021

Corrective Action: _____

Date: _____

Facility ID: 274342 Type: WELL API Number: 103-10528 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last produced 7/2021

Corrective Action: _____

Date: _____

Facility ID: 274343 Type: WELL API Number: 103-10527 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action: _____

Date: _____

Facility ID: 274344 Type: WELL API Number: 103-10526 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last produced 7/2021

Corrective Action: _____

Date: _____

Facility ID: 274346 Type: WELL API Number: 103-10524 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last produced 5/2021

Corrective Action: _____

Date: _____

Facility ID: 279500 Type: WELL API Number: 103-10627 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last produced 7/2021

Corrective Action: _____

Date: _____

Facility ID: 279501 Type: WELL API Number: 103-10626 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: [Last produced 2/2021](#)

Corrective Action: _____

Date: _____

Facility ID: 279502 Type: WELL API Number: 103-10625 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: [Last produced 3/2021](#)

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Check Dams				

Comment: 1. Fill slope erosion/sediment migrationCorrective Action: Install or repair required BMPsDate: 12/31/2021Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402853177	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564077
700703426	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564073