

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/26/2021

Submitted Date:

10/26/2021

Document Number:

700703425

FIELD INSPECTION FORM

Loc ID Inspector Name: On-Site Inspection ☐
 335695 Ramsey, Scott 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments
 2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281622	WELL	SI	08/01/2021	GW	103-10656	PICEANCE CREEK UNIT T75X-3G1	SI
281623	WELL	PR	08/01/2021	GW	103-10657	PICEANCE CREEK UNIT T75X-3G3	PR
281624	WELL	PR	08/01/2021	GW	103-10658	PICEANCE CREEK UNIT T75X-3G4	PR
281625	WELL	PR	08/01/2021	GW	103-10659	PICEANCE CREEK UNIT T75X-3G5	PR
281627	WELL	PR	02/01/2020	GW	103-10661	PICEANCE CREEK UNIT T75X-3G7	PR
281628	WELL	PR	03/01/2021	GW	103-10662	PICEANCE CREEK UNIT T75X-3G2	PR
281629	WELL	PR	08/01/2012	GW	103-10663	PICEANCE CREEK UNIT T75X-3G8	PR
281630	WELL	PR	11/01/2019	GW	103-10664	PICEANCE CREEK UNIT T75X-3G9	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 10/25/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus PCU T75X-3G, at Location # 335695 in Rio Blanco county Colorado.

While there, I observed well was shut in. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Random debris
 2. Lack of battery signage
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Comply with rule 605.e	Date:	01/26/2022
Type	OTHER		
Comment:	Location entrance		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:		
Type	DEBRIS	
Comment:	1. Random debris	
Corrective Action:	Remove debris	Date: 11/05/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 3	
Comment:	Chemical tanks in plastic containments	
Corrective Action:		Date:
Type: Plunger Lift	# 8	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 8	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 281622 Type: WELL API Number: 103-10656 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Last produced 7/2021

Corrective Action: _____ Date: _____

Facility ID: 281623 Type: WELL API Number: 103-10657 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action: _____ Date: _____

Facility ID: 281624 Type: WELL API Number: 103-10658 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action: _____ Date: _____

Facility ID: 281625 Type: WELL API Number: 103-10659 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action: _____ Date: _____

Facility ID: 281627 Type: WELL API Number: 103-10661 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action: _____ Date: _____

Facility ID: 281628 Type: WELL API Number: 103-10662 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action: _____ Date: _____

Facility ID: 281629 Type: WELL API Number: 103-10663 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action: _____ Date: _____

Facility ID: 281630 Type: WELL API Number: 103-10664 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402853183	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564083
700703429	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564076