

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2021

Submitted Date:

10/26/2021

Document Number:

700703431

FIELD INSPECTION FORM

Loc ID 335696 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284148	WELL	PR	08/01/2021	GW	103-10729	PICEANCE CREEK UNIT 297-10A5	PR
284149	WELL	PR	05/11/2009	GW	103-10730	PICENACE CREEK UNIT 297-10A6	PR
284150	WELL	SI	08/01/2021	GW	103-10731	PICEANCE CREEK UNIT 297-10A7	SI
284151	WELL	SI	08/01/2021	GW	103-10732	PICEANCE CREEK UNIT 297-10A1	SI
284152	WELL	PR	08/01/2021	OG	103-10733	PICEANCE CREEK UNIT 297-10A3	PR
284153	WELL	SI	08/01/2021	GW	103-10734	PICEANCE CREEK UNIT 297-10A8	SI
284155	WELL	PR	06/01/2020	GW	103-10735	PICEANCE CREEK UNIT 297-10A9	PR
284156	WELL	PR	08/01/2019	GW	103-10736	PICEANCE CREEK UNIT 297-10A4	PR
296376	WELL	PR	10/01/2019	GW	103-11309	PICEANCE CREEK UNIT 297-10A10	PR

General Comment:

COGCC Inspection Report Summary

On Monday 10/25/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus PCU 297-10A, at Location # 335696 in Rio Blanco county Colorado.

While there, I observed well was shut in. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Random debris
2. One dead man is not marked properly
3. Lack of battery signage

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Location entrance		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Comply with rule 605.e	Date:	01/26/2022
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	11/05/2021

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 3	
Comment:	Chemical tanks in plastic containments	
Corrective Action:		Date:
Type: Deadman # & Marked	# 5	
Comment:	One dead man is not marked properly	
Corrective Action:	Mark or remove dead man	Date: 11/26/2021
Type: Bradenhead	# 9	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	284148	Type:	WELL	API Number:	103-10729	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284149	Type:	WELL	API Number:	103-10730	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284150	Type:	WELL	API Number:	103-10731	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:	<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:	Last produced 7/2021								
Corrective Action:						Date:			
Facility ID:	284151	Type:	WELL	API Number:	103-10732	Status:	SI	Insp. Status:	SI
Producing Well									
Comment:	Last produced 7/2021								
Corrective Action:						Date:			
Facility ID:	284152	Type:	WELL	API Number:	103-10733	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284153	Type:	WELL	API Number:	103-10734	Status:	SI	Insp. Status:	SI
Producing Well									
Comment:	Last produced 7/2021								
Corrective Action:						Date:			
Facility ID:	284155	Type:	WELL	API Number:	103-10735	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284156	Type:	WELL	API Number:	103-10736	Status:	PR	Insp. Status:	PR

<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
Facility ID:	296376	Type:	WELL
API Number:	103-11309	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402853906	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564700
700703436	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564695