

Inspection Photos

11/01/2021

Operator: NONSUCH NATURAL GAS INC

#10163

Location ID: 453726

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 453726



November 1, 2021
39.5139658N 108.19599235W

Photo 1: Photo shows Nonsuch equipment on the Location. Previous inspections required Operator to submit a Form 4 w/ records identifying equipment's (Methanol tank, separator, meter shed) current status and use for production on the Location by 10/2/2020; Operator failed to submit a Form 4 with records. Inspection #696202916 required Operator to comply with Rule 606.a and remove equipment not necessary for use on the Location. To date, records have not been submitted and equipment has not been removed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC #10163
Location ID: 453726



November 1, 2021
39.51405444N 108.19601354W



November 1, 2021
39.51406739N 108.19600529W

Photo 2: Previous inspections observed that protection equipment to prevent wildlife access to the secondary containment BMPO at the 500 gallon methanol tank, and the separator stack was missing or insufficient. Photos show wildlife protection equipment remains missing or insufficient.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 453726



Photo 3: Photo shows unused equipment remains improperly stored on the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 453726



November 1, 2021
39.51369559N 108.19597081W

Photo 4: Photo taken from the east end of the Location, facing east. Photo shows stormwater runoff from the Location has resulted in erosion degradation at the Location entrance, and the access road; required stormwater and erosion control measures pursuant to Rule 1002.f remain missing or insufficient.

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC #10163
Location ID: 453726



November 1, 2021
39.51369639N 108.1958589W

Photo 5: Photo taken from the east end of the Location, facing south. Photo shows stormwater runoff from the Location has resulted in erosion degradation at the Location entrance, and the access road; required stormwater and erosion control measures pursuant to Rule 1002.f remain missing or insufficient.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 453726



Photo 6: Photo taken from the access road, facing east. Photo shows stormwater runoff from the Location has resulted in erosion degradation at the Location entrance, and the access road; required stormwater and erosion control measures pursuant to Rule 1002.f remain missing or insufficient.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 453726



Photo 7: Photo taken from the access road, facing south. Photo shows stormwater runoff from the Location has resulted in erosion degradation at the Location entrance, and the access road; required stormwater and erosion control measures pursuant to Rule 1002.f remain missing or insufficient.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 453726



Photo 8: Photo taken from the access road, facing south. Photo shows stormwater runoff from the Location has resulted in erosion degradation at the Location entrance, and the access road; required stormwater and erosion control measures pursuant to Rule 1002.f remain missing or insufficient.

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC #10163
Location ID: 453726



November 1, 2021
39.51346015N 108.19562481W

Photo 9: Photo taken from access road east of the Location, facing north. Photo shows “fork” in access road, with the left fork leading the Location, and the right fork leading to addition O&G Locations. Photos shows that the Nonsuch Location is the source of the stormwater runoff causing the erosion degradation along the access road; hill on access road (arrow) prevents stormwater runoff traveling south.