

# Inspection Photos

API: 061-06027

Operator: WESTERN OPERATING COMPANY

Inspection Date: 10/27/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06027 | Date: 10/27/2021

## Inspection Photos



**Photo 1.** Aerial imagery shows the impacted spill area at yellow arrow and red arrow. There is undesirable weed and bare soil within these area that have not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06027 | Date: 10/27/2021

## Inspection Photos



**Photo 2.** Facing southwest at the former spill area near the access road shown by yellow arrow in the previous photo. This area consists of only undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06027 | Date: 10/27/2021

## Inspection Photos



**Photo 3.** Facing southwest at the former spill area. There is no vegetation growth along this area approx. 100'x60'.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06027 | Date: 10/27/2021

## Inspection Photos



**Photo 4.** View of groundcover shows only undesirable weed growth (Kochia sp.) which is capable of growing in impacted soils. No perennial desirable vegetation was observed in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06027 | Date: 10/27/2021

## Inspection Photos



**Photo 5.** Facing northeast at the former spill area near the access road. This area consists of only undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06027 | Date: 10/27/2021

## Inspection Photos



**Photo 6.** There are four posts that remain around the impacted area indicating this area was previously fenced.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06027 | Date: 10/27/2021

## Inspection Photos



**Photo 7.** Facing north toward the surrounding undisturbed pasture which consists of native Blue grama grass prairie.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06027 | Date: 10/27/2021

## Inspection Photos



**Photo 8.** Facing southwest toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06027 | Date: 10/27/2021

## Inspection Photos



**Photo 9.** Facing southwest toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06027 | Date: 10/27/2021

## Inspection Photos



**Photo 10.** Approximately 400' northwest of the well site is another impacted area shown by red arrow in aerial photo 1. This area consists of only undesirable weeds.

