

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2021

Submitted Date:

11/03/2021

Document Number:

695105068

FIELD INSPECTION FORM

Loc ID 334236 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections
Kosola, Jason		jason.kosola@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89161	WELL	PR	04/24/1999	GW	071-06740	DAN 43-30 TR	PR
217659	WELL	PR	05/28/1998	GW	071-06438	DAN 43-30	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Vertical Separator # 2

Comment:

Corrective Action:

Date:

Type: Gas Meter Run # 2

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Deadman # & Marked # 6

Comment:

Corrective Action:

Date:

Type: Progressive Cavity # 2

Comment:

Corrective Action:

Date:

Type: Prime Mover # 2

Comment:

Corrective Action:

Date:

Type: Bradenhead # 2

Comment: BOTH ARE PLUMBED TO SURFACE

Corrective Action:

Date:

Type: Ancillary equipment # 2

Comment: TELEMETRY EQUIPMENT

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 89161 Type: WELL API Number: 071-06740 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 217659 Type: WELL API Number: 071-06438 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: _____ Lat: 37.226620 Long: -104.706780

Reference Point: SE Other: _____ Length: 70 Width: 30

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: NONE

Corrective Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Date: _____

COGCC Comments

Comment	User	Date
WELLSIGHT HAS 1 PRODUCED WATER PIT NEAR THE TR WELLHEAD ON THE SOUTHWEST SIDE OF LOCATION. THERE IS NO PIT PERMIT ASSOCIATED WITH TO THIS LOCATION ON SCOUT CARD. CONTACT EPS TO RESOLVE THIS ISSUE.	beardslt	11/03/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695105069	INPS. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5571532