

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION Receive Date: 08/31/2021 Document Number: 402797275

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

OGCC Operator Number: 10459 Contact Person: Nathan Bennett Company Name: EXTRACTION OIL & GAS INC Phone: (720) 354-4616 Address: 370 17TH STREET SUITE 5200 Email: nbennett@extractionog.com City: DENVER State: CO Zip: 80202 Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No [ ]

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 462729 Location Type: Production Facilities Name: AYLOR-61S67W Number: 20NWSE County: ADAMS Qtr Qtr: NWSE Section: 20 Township: 1S Range: 67W Meridian: 6 Latitude: 39.949268 Longitude: -104.909847

Description of Corrosion Protection

Extraction's Corrosion Protection program meets or exceeds the requirements of Rule 1104 (Integrity Management). Coating materials will be used that minimize internal and external corrosion, such as internally coated pipe or stainless steel for water service and externally coated FBE on all buried steel pipe. If flowlines are repaired due to corrosion, Extraction will investigate the failure, promptly respond with the appropriate remedial actions and determine the root cause and apply corrective actions as necessary. Extraction retains records of its chemical program in the form of Failure Analysis Reports, records of chemical invoices and chemical delivery.

Description of Integrity Management Program

Extraction's Corrosion Protection program meets or exceeds the requirements of Rule 1104 (Integrity Management). Prior to beginning any project involving flowlines, Extraction ensures the project plans, flowline installation and operation, flowline maintenance (including repairs) and all flowline inspection and testing projects meet the requirements. All pressure tests on flowlines will be conducted by an independent, third party qualified to do such testing. Precautions shall be taken to protect employees and the general public.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 462794 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**Equipment at End Point Riser: Separator**Flowline Start Point Location Identification**Location ID: 319827 Location Type: Well Site   
Name: AYLOR-61S67W Number: 20NESECounty: ADAMS No Location IDQtr Qtr: NESE Section: 20 Township: 1S Range: 67W Meridian: 6Latitude: 39.948599 Longitude: -104.906022Equipment at Start Point Riser: Well**Flowline Description and Testing**Type of Fluid Transferred: Multiphase Pipe Material: Fiberglass Max Outer Diameter:(Inches) 2.375Bedding Material: Native Materials Date Construction Completed: 09/11/1974Maximum Anticipated Operating Pressure (PSI): 55 Testing PSI: 55Test Date: 11/18/2018**OFF LOCATION FLOWLINE Abandonment Verification**Date: 06/07/2021**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

**Description of Abandonment Verification:**

The flowline serving the Aylor 3 well (API #05-001-06896) was removed in its entirety. Approximately 1178' of ~3" fiberglass pipeline (buried +/- 4' deep) was removed, the trench was backfilled, and the land surface was graded.

**FLOWLINE FACILITY INFORMATION**Flowline Facility ID: 462793 Flowline Type: Wellhead Line Action Type: \_\_\_\_\_**OFF LOCATION FLOWLINE REGISTRATION**Equipment at End Point Riser: Separator**Flowline Start Point Location Identification**Location ID: 319865 Location Type: Well Site   
Name: AYLOR-61S67W Number: 20SWSECounty: ADAMS No Location IDQtr Qtr: SWSE Section: 20 Township: 1S Range: 67W Meridian: 6Latitude: 39.944839 Longitude: -104.910102Equipment at Start Point Riser: Well**Flowline Description and Testing**Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375Bedding Material: Native Materials Date Construction Completed: 07/12/1975Maximum Anticipated Operating Pressure (PSI): 35 Testing PSI: 35Test Date: 04/05/2018

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: 01/14/2019

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

The Steel 2" and the Poly 1" were both flushed out then cut and capped approx 4' below grade.

**OPERATOR COMMENTS AND SUBMITTAL**

Comments This Form 44 is being submitted for one (1) Flowline Abandonment. The subject flowline was removed in its entirety. Details are as follows:

00106896FL

- Previously serviced the Aylor #3 well (API #05-001-06896).
- Updated GIS SHAPEFILE attached.
- Recent PRESSURE TEST attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: \_\_\_\_\_ Date: 08/31/2021 Email: nbennett@extractionog.com

Print Name: Nathan Bennett Title: Regulatory Manager

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved:  **Director of COGCC** Date: 11/4/2021

## Conditions of Approval

**COA Type**

**Description**

--	--

### Attachment Check List

**Att Doc Num**

**Name**

402797275	Form44 Submitted
402797277	OFF-LOCATION FLOWLINE GIS SHP
402797285	PRESSURE TEST

Total Attach: 3 Files

### General Comments

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval

Total: 0 comment(s)