

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2021

Submitted Date:

10/29/2021

Document Number:

688801010

**FIELD INSPECTION FORM**Loc ID 320864 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 900

Name of Operator: ALAMOSA DRILLING INC

Address: 8150 N. CENTRAL EXPY - STE 750

City: DALLAS State: TX Zip: 75205-

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlutz, Scott		scott.schultz@coag.gov	
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Mercer, Lauren		lauren.mercer@coag.gov	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205262	WELL	PR	07/01/2020	OW	007-06141	NIELSEN 5	EI

**General Comment:**

On October 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Nielson #5. For the most recent field inspection report of this facility, please refer to document #688800016.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Well head accessed by walking through agricultural field.			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Sign has been updated to include information required by Inspection Document #688800016.			
Corrective Action:				Date:
Type	BATTERY			
Comment:	Sign has been updated to include information required by Inspection Document #688800016.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	AST is labeled with contents, capacity, and has NFPA placard.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Emergency contact information has been added to signage as required by Inspection Document #688800016.			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PUMP JACK			
Comment:	Post and wire perimeter fencing around pump jack and well head.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Flow Line	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Electric motor.			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:	Operating during this inspection.			

Corrective Action:		Date:	
--------------------	--	-------	--

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS			37.017703,-106.876876

Comment:	
----------	--

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate

Comment:	Uncompacted earthen berm around AST.
----------	--------------------------------------

Corrective Action:	Secondary containment is not sufficiently impervious to contain spilled or released materials.	Date:	11/29/2021
--------------------	--	-------	------------

**Wells Served By Facilities Above**

API Number
007-06141

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 205262    Type: WELL    API Number: 007-06141    Status: PR    Insp. Status: EI

**COGCC Comments**

Comment	User	Date
<p>On October 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Nielson #5. For the most recent field inspection report of this facility, please refer to document #688800016.</p> <p>Signs have been updated to include information required by Inspection Document #688800016.</p> <p>Emergency contact information has been added to signage as required by Inspection Document #688800016.</p> <p>Uncompacted earthen berm around AST does not appear to be sufficiently impervious to contain releases.</p>	hughesjo	10/29/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402857892	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568395">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568395</a>
688801011	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568388">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568388</a>