

# TEP RWF 513-10 Location # 335655



location



location



TEP  
RWF 513-10  
Location # 335655



location



Lack of stabilization/compaction





TEP  
RWF 513-10  
Location # 335655



**Lack of stabilization/compaction**



**Lack of stabilization/compaction**



TEP  
RWF 513-10  
Location # 335655



**Load out line missing cap/bull plug**



**Load out line missing cap/bull plug**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

TEP  
RWF 513-10  
Location # 335655



**Load out line missing cap/bull plug**



**Load out line missing cap/bull plug**





TEP  
RWF 513-10  
Location # 335655



**Load out line missing cap/bull plug, leaking and  
bucket full of fluid**



**bucket full of fluid and spilling out**



TEP  
RWF 513-10  
Location # 335655



Unmarked tanks



Unmarked tanks





TEP  
RWF 513-10  
Location # 335655



Lack of stabilization/erosion



Lack of stabilization/erosion





TEP  
RWF 513-10  
Location # 335655



**Lack of stabilization/erosion**



**Lack of stabilization/compaction**





TEP  
RWF 513-10  
Location # 335655



Debris



Debris