



**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	PHOTO 3: SOLAR PANEL IS PARTIALLY COVERING WELL SIGN.		
Corrective Action:	ADJUST SOLAR PANEL OR MOVE WELL SIGN SO SIGN CAN BE EASILY SEEN FROM A DISTANCE PER RULE 605.a.	Date:	12/04/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	PHOTO 4: VEGETATION IS NOT BEING MAINTAINED.		
Corrective Action:	MAINTAIN VEGETATION PER RULE 606.	Date:	12/04/2021

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:	HAS MARKER		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	telemetry equipment		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS PLUMBED TO SURFACE		

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 281855 Type: WELL API Number: 071-08641 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: WELL LAST PRODUCED DEC. 2020.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Fail			
Drains	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Fail			

Comment: PHOTO 5 & 6: STORMWATER HAS BYPASSED A BMP JUST OFF LOCATION AND CAUSING RUTTING ON ROW.

Corrective Action: Install or repair required BMPs per Rule 1002. SERIES RULES.

Date: 12/04/2021

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID: 286550      Lat: 37.216660      Long: -104.692000

Reference Point: SE      Other: \_\_\_\_\_      Length: 30      Width: 15

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: None      Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment: NONE

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: NO      Oil Accumulation: NO      2+ feet Freeboard: NO

Comment: PHOTO 7: FLUID LEVEL IN PRODUCED WATER PIT IS ABOVE FREEBOARD.

Corrective Action IMMEDIATELY LOWER FLUID LEVEL IN PIT AND MAINTAIN FLUID LEVEL A MINIMUM OF 2' BELOW GROUND LEVEL PER RULE. 909.c.

Date: 11/05/2021

Permit:	Facility ID	Permit Num	Expiration Date
	286550	1395838	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695105089	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5574511">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5574511</a>