

Location

Overall Good:

Signs/Marker:

Type	OTHER				
Comment:	PHOTO 2: WELL SIGN/ BOTH SIGNS ARE FOR THE TR WELL THERE IS NOT A SIGN POSTED FOR THE VERMAJO WELL.				
Corrective Action:	Install sign to comply with Rule 605.a.			Date:	12/04/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

					corrective date
Type: Progressive Cavity	# 2				
Comment:					
Corrective Action:					Date:
Type: Vertical Separator	# 2				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 2				
Comment:	BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.				
Corrective Action:					Date:
Type: Bradenhead	# 2				
Comment:	BOTH ARE PLUMBED TO SURFACE				
Corrective Action:					Date:
Type: Deadman # & Marked	# 8				
Comment:					
Corrective Action:					Date:
Type: Ancillary equipment	# 2				
Comment:	TELEMETRY AND ELECTRIC DRIVE EQUIPMENT				
Corrective Action:					Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 89160 Type: WELL API Number: 071-06739 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 217747 Type: WELL API Number: 071-06526 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 263024 Type: PIT API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 263024 Lat: 37.239326 Long: -104.709791

Reference Point: SE Other: _____ Length: 100 Width: 40

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: NONE

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	420923	200288776	
	263024	852642	
	420923	200288776	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
695105092	INSP. PHOTOS	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5574512