

KTM Operating LLC, Craig 12-33  
073-06365  
Inspection #688311500  
11/2/2021  
Reinspection



Colorado Oil and Gas Conservation Commission  
38.87091, -103.56952, 5003.3ft, 230°  
11/02/2021 02:29:03 PM

400 BBL OIL



CRCT  
302879



Colorado Oil and Gas Conservation Commission  
38.87097, -103.56937, 5072.2ft, 191°  
11/02/2021 02:27:26 PM





Colorado Oil and Gas Conservation Commission  
38.87096, -103.56956, 5019.7ft, 187°  
11/02/2021 02:27:36 PM




Colorado Oil and Gas Conservation Commission  
38.87095, -103.56958, 5026.2ft, 179°  
11/02/2021 02:27:39 PM





Colorado Oil and Gas Conservation Commission  
38.87095, -103.56961, 5026.2ft, 174°  
11/02/2021 02:27:47 PM

A close-up photograph of a metal weld joint. The upper portion of the image shows a light-colored, possibly galvanized, metal surface. A dark, irregular weld line runs diagonally across the middle. Below the weld, the metal is heavily corroded, showing a dark, pitted, and rusted surface. The text is overlaid on the bottom right of the image.

Colorado Oil and Gas Conservation Commission  
38.87094, -103.56961, 5032.8ft, 163°  
11/02/2021 02:27:51 PM





Colorado Oil and Gas Conservation Commission  
38.87104, -103.56956, 5019.7ft, 205°  
11/02/2021 02:28:26 PM